



FAG



FAG 0516

SERVICE INFO

VAG Wheel bearing removal

Manufacturers: Audi
Seat
Volkswagen

Model: A4, A5, A6, A7,
A8 Q5, R8
Exeo
Passat

Part No.: 713 6109 00



On the above vehicles the wheel bearing assembly can become seized within the aluminium suspension unit. This is due to a difference in composition between the arm and carrier, also known as galvanic corrosion. This is often overcome by force which can fracture the wishbone or damage the steering knuckles and ball joints.

Tools are available in the aftermarket to ensure these bearing assemblies can be removed without causing damage to the associated parts. The tool shown is a Sykes-Pickavant version.



- For accurate model information please see LuK catalogue
- Die genaue Fahrzeugzuordnung entnehmen Sie bitte dem LuK-Katalog
- Pour plus d'information sur les applications veuillez vous référer au catalogue LuK
- Para obtener información sobre el modelo, rogamos consulte el catálogo de LuK
- Per informazioni sul modello consultare il catalogo LuK

Phone : +44 (0) 1432 264 264
Fax : +44 (0) 1432 375 760
E-Mail : hfd-pm@schaeffler.com
www.schaeffler-aftermarket.co.uk